

Photos 1 to 8 were taken from the centre of the site while Photos 9 and 10 were taken from positions surrounding the study site.



Photo 1: View towards the north indicating the disturbance present on site.



Photo 2: View towards the south indicating one of existing access roads on site.



Photo 3: View towards the east with stockpiles visible in background.



Photo 4: View towards the west with signs of disturbance visible



Photo 5: View towards the north west.



Photo 6: View towards the north east.



Photo 7: View towards the south east.



Photo 8: View towards the south west.



Photo 9: View from the west looking east at the existing tailings dumps on the site



Photo 10: View from the north looking south at the existing tailings dumps on the site