











General Site photographs



Figure 1: Nelspruit Railway Station – General view



Figure 2: Nelspruit Railway Station – Goods Shed



Figure 3: View of the Barberton Railway Station (Inactive) – Goods Shed – this view is towards the mountains where the old conveyor belt ran across to bring the raw asbestos from the mine to be transported by rail (beyond the mountains is where asbestos mine was located)



Figure 4: Photo of the area where the old Barberton railway station building occurred, which has been demolished



Figure 5: General view – Komatipoort Railway Station



Figure 6: General view towards the west yard – Komatipoort Railway Station. This view is from the non-perennial stream that runs through the station



Figure 7: Komatipoort Railway Station. This view is towards the non-perennial stream that runs through the station, which feeds into the Komati River (the Komati River is outside of the railway station)



Figure 8: Komatipoort Railway Station - West yard



Figure 9: Komatipoort Railway Station - Residential area built next to the west yard