

Proposed Remediation of Asbestos Contaminated Land on the Nsele Railway Station in KwaZulu-Natal



North West




North



North East



West



East



South West




South



South East







3. English and Afrikaans site notices placed on the notice board of the yard masters office at the Nseso Yard, where all general workers have to sign in for duty.





4. General area of the Nseso railway Station. Area is completely transformed with little, to none natural soils on site.



5. The area surrounding the Nseso railway station is used for timber and sugar cane production (not clear in these images).